


C20.01



start you this part equipped
on your machine?

This is the newer model - you need it
for the quick fit line -

you order

Rep Code	Désignation
1 980323	Support rapide 3 mo
2 722637	Vis choc m16x1,5 lg 70 10,9
3 722635	Axe rapide 3
4 722636	Goupille rapide 3
5 720341	Plat de serrage dent entraxe 65
6 980319	Dent rapide 3 g
7 980320	Dent rapide 3 d
8 721407	Goupille de securite d12.5 zn
9 722634	Outil rapide 3